



GREAT-TOOLS.RENT

Bestandsliste 321395/0033

Ersatzteilbox Plasma Powermax 1650

3	ST	321399/0012	Schutzschild Powermax 1650 /100A 220065
2	ST	321399/0003	Brennerkappe Powermax 1650 /100A
3	ST	321399/0005	Schneiddüse Powermax 1650 /100A
3	ST	321399/0009	Elektrode Powermax 1650 /100A 120932
2	ST	321399/0007	Gaswirbelring Powermax 1650 /100A
1	ST	321399/0049	Adapter Klauenkupplung Powermax

Positionen: 6
